03500.015739. (APR 2 9 2005

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

in re Patent of:)	
	:	Examiner: Lam Nguyen
NOBUYUKI MATSUMOTO ET AL.)	
	:	Art Unit: 2853
Appln. No.: 09/944,137)	
	:	
Filed: September 4, 2001)	
	:	
For: LIQUID DISCHARGE HEAD, LIQUID)	
DISCHARGE APPARATUS, VALVE	:	
PROTECTION METHOD OF THE)	
SAME LIQUID DISCHARGE HEAD	:	
AND MAINTENANCE SYSTEM)	
	:	
U.S. Patent No.: US 6,827,416 B2	,	
0.5.1 dtollt 140 05 0,027,410 D2	•	
January December 7, 2004		A
Issued: December 7, 2004)	April 28, 2005

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Leonard P. Diana Attorney for Patentees Registration No. 29,296

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

NY_Main 492581v1

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

US 6,827,416 B2

DATED

December 7, 2004

INVENTOR(S) :

NOBUYUKI MATSUMOTO ET AL.

Page 1 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1:

Line 15, "a" should read --the--;

Line 18, "accompanied" should read --in response to--;

Line 19, "by" should be deleted;

Line 26, "giving" should read --application of--; and "allowed to" should read --caused to undergo--;

Line 27, "produce" should be deleted;

Line 34, "discharge" should read --discharging--;

Line 39, "a" should be deleted;

Line 42, "in" should read --at a--;

Line 48, "even come to be used as far as" should read --has even come to be used--;

Line 61, "high quality" should read --a high-quality--; and

Line 63, "forgiving an" should read --for providing a--.

COLUMN 2:

Line 26, "liquid" should read --of the liquid--; and

Line 29, "y" should be deleted.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

PATENT NO. <u>US 6,827,416 B2</u>

No. of add'l. copies @ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,827,416 B2

DATED

December 7, 2004

INVENTOR(S) :

NOBUYUKI MATSUMOTO ET AL.

Page 2 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 3:

Line 1, "an" should be deleted;

Line 58, "Each configuration" should read -- The configurations--;

Line 59, "an" should read --a--; and

Line 66, "8 and the" should read --8 and--; and "as" should be deleted.

COLUMN 4:

Line 9, "to" should read --at--;

Line 26, "as" should read --as a--;

Line 37, "were" should read --was--; and

Line 46, "its" should read --it's--.

COLUMN 5:

Line 24, "that" should be deleted;

Line 28, "in creases" should read --increases--;

Line 39, "the" should read --a--;

Line 50, "defect," should read --defect.--;

Line 53, "can" should read --to--; and "the" should be deleted; and

Line 57, "the" should be deleted.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

PATENT NO. US 6,827,416 B2

No. of add'l. copies @ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,827,416 B2

DATED

December 7, 2004

INVENTOR(S) :

NOBUYUKI MATSUMOTO ET AL.

Page 3 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 6:

Line 39, "discharge" should read --discharging--;

Line 49, "relates to" should read --includes--; and

Line 60, "relates to" should read --includes--.

COLUMN 7:

Line 25, "and like" should be deleted.

COLUMN 8:

Line 11, "head" should read --head)--;

Line 30, "a" should be deleted;

Line 49, "the material of" should read --a material of the--;

Line 62, "member" should read --members--; and

Line 63, "to" should be deleted.

COLUMN 9:

Line 1, "ember" should read --member--;

Line 2, "an" should read --a--;

Line 4, "heart" should read --heat--;

Line 6, "to" should read --of--;

Line 33, "to" should read --in--; and

Line 39, "a" should be deleted.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

PATENT NO. US 6,827,416 B2

No. of add'l. copies @ 30¢ per page

□

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,827,416 B2

DATED

December 7, 2004

INVENTOR(S) :

NOBUYUKI MATSUMOTO ET AL.

Page 4 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 10:

Line 6, "with the result of" should read --if the result of detection indicates--; and

Line 16, "show the" should read --are--.

COLUMN 11:

Line 1, "element" should read --elements--;

Line 6, "tens" should read --tens of--;

Line 22, "an" should read --a--; and

Line 23, "damages of" should read --damage to--.

COLUMN 12:

Line 33, "at" should read --in--; and

Line 61, "inch" should read --inches--.

COLUMN 14:

Line 11, "a" should be deleted;

Line 24, "disk" should read --disks--;

Line 35, "disk," should read --disks,--;

Line 37, "a" should be deleted;

Line 39, "a" should be deleted;

Line 40, "a" should be deleted; and

Line 41, "a" should be deleted.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

PATENT NO. US 6,827,416 B2

No. of add'l. copies @ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

US 6,827,416 B2

DATED

December 7, 2004

INVENTOR(S) :

NOBUYUKI MATSUMOTO ET AL.

Page 5 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 15:

Line 2, "and the" should read --and--; and Line 4, "to" should read --on--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. <u>US 6,827,416 B2</u>

No. of add'l. copies @ 30¢ per page



Form PTO 1050 (Rev. 3-82)

NY_Main 492581v1